

95-7/24/02

10

**QCC Code Logic for BSM**

**Quality Control Codes**

- First Position (Contract Quality Requirements)**
- A Contract Quality Requirements further defined. Refer to Quality Guidance / Contract Guidance Text
  - B Commercial (Any System Offered)
  - C Contractor Responsibility
  - D Standard Inspection (Clause 52.246-2)
  - E Higher Level Contract Quality Tailored ISO 9000
  - F Higher Level Contract Quality ISO 9000 (Clause 52.246-11)
  - G Commercial - First Article Testing Government
  - H Contractor Responsibility - First Article Testing Government
  - J Standard Inspection - First Article Testing Government
  - K Higher Level Contract Quality Tailored ISO 9000 - First Article Testing Government
  - L Higher Level Contract Quality ISO 9000 - First Article Testing Government
  - M Commercial - First Article Testing Contractor
  - N Contractor Responsibility - First Article Testing Contractor
  - P Standard Inspection - First Article Testing Contractor
  - Q Higher Level Contract Quality Tailored ISO 9000 - First Article Testing Contractor
  - R Higher Level Contract Quality ISO 9000 - First Article Testing Contractor

**Second Position (Quality Subsystem Identification)**

- A No Quality Subsystem Requirements
- B Product Verification Testing (PVT)-The contractor is responsible for ensuring that supplies are manufactured, produced, and subjected to all tests required by applicable material specifications/ drawings specified in the purchase description of this contract. Notwithstanding any other clause to the contrary, and/or in addition thereto, the Government reserves the right to conduct PVT to ascertain if any or all requirements of the purchase identification description contained elsewhere herein are met prior to final acceptance. (Clause 52.246-9004)
- C Measurement and Test Equipment (M/TE)-the M/TE clause requires the contractor ensure that the gauges and other testing equipment used in determining whether the supplies presented to the government for acceptance under this contract fully conform to specified technical requirements and are calibrated in accordance with ISO 10012-1 or ANSINCLS Z540-1. (Clause 52.246-9003)
- D Certificate of Conformance (COC) (Clause 52.246-15)
- E Product Verification Testing / Measurement and Test Equipment (PVT / MTE)
- F Product Verification Testing / Certificate of Conformance (PVT / COC)
- G Product Verification Testing / Measurement and Test Equipment / Certificate of Conformance (PVT / MTE / COC)
- H Measurement and Test Equipment / Certificate of Conformance (MTE / COC)

**QCC Code Logic for BSM**

**Third Position (Quality Specific requirements)**

*NSN specific*

- A** No Specific requirements
- B** Calibration System Requirements-the contractor is required to have a calibration system which complies with industry standards. **NOTE:** Not applicable with Higher Level Inspection.
- C** Quality Assurance Letter of Instruction (QALI)
- D** Preaward Survey
- E** Postaward Conference (Clause 252.242-7000)
- F** Shelf Life - Depots Storage Standard Actions (Clause 52.211-9G01)
- G** Statistical Process Control (SPC) (Clause 52.246-9002)
- H** Controlled Industrial Material / Industrial Material Quality Improvement Program (CIM/IMQIP)
- J** Deliverable Data - DD 1423 (Clause 52.227-9G08)
- K** Two or more codes apply
- L** Local Clause(s) apply. Refer to Quality Guidance / Contract Guidance Text.
- M** One or more codes and local clause(s) apply
- N** Dermatology and Toxicity
- P** Additional Requirements - Refer to Quality Guidance / Contract Guidance Text

**REMINDER: QAPs are In Option E**

**NOTE: When two or more codes/clauses apply, annotate in Option N what codes and/or clauses are used.**

**POC**  
**Mary Ellen Carhart**  
**Quality Assurance Specialist**  
**OZS**  
**5845**